



Catchment Location







Percentage Area of Classes

Degraded Class - Land-cover Map for the Mtata Catchment

0 3 6 Kilometers



 Rivers and Dams

-  Dongas & sheet erosion scars
-  Degraded: forest and woodland
-  Degraded: thicket & bushland (etc)
-  Degraded: unimproved grassland
-  Degraded: shrubland and low Fynbos
-  Degraded: hermland

Data Source: Land-cover: SA National Land-cover Database 1994-1996
 Rivers: Chief Directorate of Surveys and Mapping, Institute for Water Quality Studies
 Projection: Albers Equal Area

