



**Catchment Location**



**Percentage Area of Classes**



**Degraded Class - Land-cover Map for the Thukela Catchment**

Rivers and Dams

- Dongas & sheet erosion scars
- Degraded: forest and woodland
- Degraded: thicket & bushland (etc)
- Degraded: unimproved grassland
- Degraded: shrubland and low Fynbos
- Degraded: hermland

0 20 40 Kilometers



Data Source: Land-cover: SA National Land-cover Database 1994-1996  
 Rivers: Chief Directorate of Surveys and Mapping, Institute for Water Quality Studies  
 Projection: Albers Equal Area

